WEST-JACKSON HOUSE 111 North Washington Street Clarksville Habersham County Georgia

HABS 64, 69-CLAVI,

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
NATIONAL PARK SERVICE
Department of the Interior
Southeast Region
Atlanta, Georgia 30303

MCKS

United States Department of the Interior Heritage Conservation and Recreation Service Washington, D.C. 20243

NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY HABS

ARCHITECTURAL DATA FORM

GA. 69-CLAVI,

		•	1-
STATE	COUNTY	TOWN OR VICINI	TY
GEORGIA	HABERSHAM	CLARKESVILLI	E
HISTORIC NAME OF STRUCTU	RE (INCLUDE SOURCE FOR NAME)	HABS NO.
WEST-JACKSON HOUSE			GA-1206
		• • • • • • • • • • • • • • • • • • •	GA-1200
SECONDARY OR COMMON NAME	S OF STRUCTURE		
COMPLETE ADDRESS (DESCRI	BE LOCATION FOR RURAL SITES)	
	reet, Clarkesville, GA (Cour		cords)
717 North Washington St	reet, Clarkesville, GA (City		ords)
DATE OF CONSTRUCTION (IN	•) (INCLUDE SOURCE)	4
Exact date unknown - ap	proximately 1890 Architect	and original owner	are unknown
SIGNIFICANCE (ARCHITECTU	RAL AND HISTORICAL, INCLUDE	ORIGINAL USE OF STRU	CTURE)
	constructed as a residence,		
	9th Century example of the H		
	portico, trimmed with Victo	orian motifs. Addition	ns were made in
the 1920's (specified b	elow)		
	wo-story Classical Revival p	portico	
MATERIAL OF CONSTRUCTION	(INCLUDE STRUCTURAL SYSTEM	S) Wood frame structu	ire; clapboard
facade with four square	wooden columns. Balloon fra	uming, diagonal sheath	ning and brick
foundation.	STOUGHURS (SVETSUSS SLAND D	LAUC ON OFBARANT BACT	C 105 4005 MAG. 6
	STRUCTURE (SKETCHED FLOOR Pidence consists of two rooms		
1920's additions create	<u>d present L-shaped structure</u>	SOVER LWO GIVIGED BY	LOOR PLAN PHOTOS)
EXTERIOR FEATURES OF NOT		. ADDE HOUDINING IN	JOUR I LARY THOTOUT
	s an outer monumental Clas <mark>si</mark>		
	ngular bracketed pediment; i		
Victorian era braces, a	nd cutwork balustrades; cent	ral gable on principa	al facade.
INTERIOR FEATURES OF NOT	E (DESCRIBE FLOOR PLANS, IF	NOT SKETCHED	· · · · · · · · · · · · · · · · · · ·
	surfaces are plastered (sev		flaking). Interio
contains four fireplaces	s, formerly with modest wood	len mantels (removed b	y van dals). The
	have been the central stairw	ay cutwork balustrade	e all of which has
been removed or destroyed MAJOR ALTERATIONS AND AD		·	
	In the I	920's, the south rear	-
	the first and second floors		
room. The present struct	first floor was lost with th ture is L-shaped.	e removal of a wall t	o create a large
PRESENT CONDITION AND US	E The structure has been va	cant since 1975. At p	resent, while a
few portions are struct	urally sound, most of the bu	ilding has been sever	cely vandalized on
damaged by neglect and n OTHER INFORMATION AS APP	numerous leaks. Plaster dama ROPRIATE		
	All alcultectural	features of note have	
	eterioration are most eviden property contains two outbui		
<u>deteriorated condition.</u>		·	
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL	REGISTER, STATE REGI	STERS, ETC.)

Property has been nominated for listing on the National Register of Historic Places, and determined eligible. Habersham County (Clarkesville) Historical Society and present owners: G.C. Jackson and Ernest Jackson. State Historic Preservation Section and APDC.

COMPILER, AFFILIATION

Ms. Dale Jaeger, Preservation Planner, Georgia Mountains APDC

Ms. Andrea Niles, Survey & Review Asst, State Historic Preservation

Section
Mr. William S. Loyd, Vice President, Cornelia Bank, Cornelia, GA

January 26, 1982

DATE